

State of Utah DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor
Kathleen Clarke
Executive Director

Michael O. Leavitt
Governor
Kathleen Clarke
Executive Director

Executive Director

Lowell P. Braxton

Division Director

801-538-5340

801-359-3940 (Fax)

801-538-7223 (TDD)

Philips

INSPECTION REPORT

Partial XXX Con	iplete _	Explorat	ion
Inspection Date:	04/19/2	2002 / Time:	9-10 AM
			: 03/15/2002

Mine Name: Horizon Mine	County: Carbon 1	Permit Number: _	C/007/020					
Permittee and/or Operator's Name: Lodestar Energy, Inc.								
Business Address: HC 35 Box 370, Helper, Utah 84526								
Company Official(s): Mr. Kit Pappas, Engin	neering Dept.							
State Official(s): Peter Hess	Federal Offic	ial(s): None						
Weather Conditions: <u>Clear / temperature in mid-thirties</u> , Fahrenheit								
Type of Mining Activity: Underground XX	X_SurfacePrep l	PlantOther						
Existing Acreage: Permitted 711 Disturbed	ed 9 Regraded	Seeded						
Status: Active								

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For <u>partial inspections</u> check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	N/A	COMMENTS	NOV/ENF	
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE					
2.	SIGNS AND MARKERS	$\overline{[X]}$	ĹÌ		\Box	
3.	TOPSOIL	<u>[X]</u>	ĹÌ		\Box	
4.	HYDROLOGIC BALANCE:					
a.	DIVERSIONS	[X]			\Box	
b.	SEDIMENT PONDS AND IMPOUNDMENTS	[X]		[X]		
c.	OTHER SEDIMENT CONTROL MEASURES	[X]		[X]		
d.	WATER MONITORING	[X]		[X]		
e.	EFFLUENT LIMITATIONS	[X]		[X]		
5.	EXPLOSIVES	[X]		[X]		
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	Ĺ	[X]			
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS					
8.	NONCOAL WASTE	[X]		[X]		
9.	PROTECTION OF FISH, WILDLIFE AND RELATED					
	ENVIRONMENTAL ISSUES					
10.	SLIDES AND OTHER DAMAGE		[X]			
11.	CONTEMPORANEOUS RECLAMATION		[X]			
12.	BACKFILLING AND GRADING		[X]			
13.	REVEGETATION		[X]			
14.	SUBSIDENCE CONTROL	[X]		[X]		
15.	CESSATION OF OPERATIONS	. [_]	[X]		[_]	
16.	ROADS:					
a.	CONSTRUCTION/MAINTENANCE/SURFACING	[X]				
b.	DRAINAGE CONTROLS	[X]				
17.	OTHER TRANSPORTATION FACILITIES	[X]			<u> </u>	
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	[X]		[X]	Ļ	
19.	AVS CHECK (4 th Quarter- April, May, June)				لِــالِ	
20.	AIR QUALITY PERMIT	[X]		[X]	لِــاِ	
21	PONDING & INCLIDANCE	ΓΊ	Г T	[]	1 1	

INSPECTION REPORT

(Continuation Sheet)

PERMIT NUMBER: <u>C/007/020</u>

DATE OF INSPECTION: 04/19/2002

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

The sediment pond contains water, the level of which is well below the primary discharge or decant elevation.

4C. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES

The permittee needs to replace two of the straw bales along the southern boundary of ASCA #1, (one at the SW corner and one at the SE), which is the topsoil storage area adjacent to the County road. Wildlife have pulled the bales out of the dike and partially consumed them.

4D. HYDROLOGIC BALANCE: WATER MONITORING

According to Mr. Pappas, the permittee has entered additional information into the Division's water monitoring database for the fourth quarter of 2001. Sixteen water-monitoring points had been reported as not having adequate information; most of these were "no flow" situations, or are no longer required to be monitored by the permit. "No Flow" has thus been entered where appropriate.

The status of the second quarter 2002 water monitoring is not known at this time.

4E. HYDROLOGIC BALANCE: EFFLUENT LIMITATIONS

Mr. Pappas indicated this day that the last grab sample that was taken of the mine water discharge (UPDES point 002A) had a reportable level of suspended solids of 7 mg/l. The discharge observed from the undisturbed bypass culvert this day was clear.

Photos of the water discharge from the undisturbed bypass culvert below the site (a combination of UPDES point 002A discharge and upper Jewkes Creek flow) can be seen in the O drive, 007020/Images/4192002.

5. EXPLOSIVES

The explosive and detonator storage magazines at the site remain empty.

8. NONCOAL WASTE

The County and the entire State have experienced high velocity winds over the past several days. As such, a few pieces of noncoal waste were observed in the Jewkes Creek drainage up canyon of the Mine site disturbed area. Mr. Pappas agreed to have the noncoal waste removed from the drainage.

A small flow was observed in Jewkes Creek above the Mine site.

INSPECTION REPORT

(Continuation Sheet)

PERMIT NUMBER: <u>C/007/020</u>

DATE OF INSPECTION: 04/19/2002

14. SUBSIDENCE CONTROL

The permittee submitted an annual subsidence report on March 7, 2002. A review conducted by this individual on April 2, 2002 indicated no vertical or horizontal displacement of any of the five monitoring points. The permittee initiated coal extraction on November 6, 2001. A map of the mine workings, as they existed on December 31, 2001, and the submitted report are P.E. certified by Mr. Dave Miller, P.E.

18. SUPPORT FACILITIES/UTILITY INSTALLATIONS

The permittee is preparing to install a portable crusher at the Horizon site to enhance their processing ability. A small portable unit is being readied.

20. AIR QUALITY PERMIT

The permittee recently met with the County Commissioners to discuss the County road leading to the Mine site. As a result, two water trucks and a road grader were observed operating on the County road improving its condition. Gravel is being placed and spread to aid in controlling fugitive dust.

Inspector's Signature:

Peter Hess #4

Date: April 22, 2002

Note:

This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc:

James Fulton, OSM David Miller, Lodestar Price Field office

O:\007020.HZN\Compliance\2002\P 0419.doc